

# 2010 CONCRETE REPAIR PROJECT (04-410)

HOUSE #	STREET NAME	Type of Work
<b>CONCRETE STREET PANEL REPAIR</b>		
2	BROAD BLVD	6"-8" panel repair
3	SINTON PL	6"-8" panel repair
4	TWINBROOK	6"-8" panel repair
5	STANBRIDGE DR	6"-8" panel repair
<b>CONCRETE CURB, SIDEWALK &amp; MEDIAN REPAIR</b>		
7	Rosewood Arts Center	6" sidewalk
8	3517 ASCOT CT	Snow plow damage of curb.
9	4401 FAR HILLS AVE	Island at driveway of Arbor S.C. (near Key Bank)
10	** E. STROOP RD	@ Leonora Drive (west leg) Curb ramps and median cut for cross walk.
11	SHROYER RD	North of Dorothy Lane Median
12	892 E STROOP RD	Southwest corner Stroop & Ackerman Place 4" sidewalk between walk & signal pole.
13	2845 HAIG AVE	Behind property, off of the alley. Place 6" parking pad.
14	SHROYER RD @ MOSSOAK DR	Both corners - replace depr curb and ramps.
15	SHROYER RD @ HOLLENDALE DR	Both corners - replace depr curb and ramps.
16	SHROYER RD @ FRIEDA LN	North corner - replace ramp. South corner - replace depr curb and ramp.
17	SHROYER RD @ GRAYSON ST	NE corner - replace depr curb and ramp.
18	SHROYER RD @ PRIMROSE LN	West corner - replace ramp. East corner - replace depr curb and ramp.
19	SHROYER RD @ LESHER LN	East corner - replace curb ramp.
20	651 WINDINGWAY	Snow plow damage of curb.
21	2243 SPRINGMILL RD	Snow plow damage of curb.
22	2287 S DIXIE HWY	NW corner - curb ramp
23	WHIPP RD	Replace truncated dome mat Whipp Rd at Oak Valley, Bigger Rd
24	Service Yard Wash rack area	6" Median
25	Service Yard Wash rack area	8" pavement around two drains
26	Service Yard Employee Parking Lot	Curb
27	Service Yard Visitor Parking Lot	Curb

## 2010 CONCRETE REPAIR PROJECT (04-410)

HOUSE #	STREET NAME	Type of Work
28	Fire Sta. 33 Drive Approach along Bobbie Place	Drive approach (1-3)
29	Fire Sta. 33 Front Driveway along Bobbie Place	Curb (4)
30	Fire Sta. 33 Front Driveway along Bobbie Place	9" pavement replacement in driveway (5-8)
31	Fire Sta. 33 Rear apron at rear garage door	9" pavement for apron at rear door (9)
32	Fire Sta. 33 Rear (west) corner of fire station	curb (10)
33	Fire Sta. 33 Steps at south corner of station	patching (11)
34	Fire Sta. 33 Training building (south of station)	patching around training building (12)
35	Fire Sta. 36 Driveway	9" pavement replacement in driveway
36	Fire Sta. 36 Apron at garage door	patching in front of garage door
<b>CATCH BASIN REPAIRS</b>		
38	571 E DOROTHY LN	Near San Rae Dr. Repair broken State CB top.
39	670 E DOROTHY LN	Across from Hazelwood Ave. Repair broken State CB top.
40	777 E DOROTHY LN	Near Oakley Ave. Repair broken State CB top.
41	1100 E DOROTHY LN	Near Oakmont Ave. Repair broken State CB top.
42	1200 E DOROTHY LN	Near Rushland Dr. Repair broken State CB top.
43	223 W DOROTHY LN	East of Roanoke Ave. Repair broken State CB top.
44	645 W DOROTHY LN	Near Patterson Blvd. Repair 2 broken State CB tops.
45	2975 SHROYER RD	northwest corner of Dorothy & Shroyer. Repair broken State CB top.
46	2584 ACORN DR	Modify existing 3A Catch Basin, As Per Plan
<b>ADDITIONAL WORK</b>		
48	3016 LOCUST CAMP RD	Snow plow damage of curb.
49	SW CORNER ROCKWELL & WHITLOCK	Snow plow damage of curb.
50	801 HOLLENDALE DR	Snow plow damage of curb.
51	4824 ALGOOD PL	Snow plow damage of curb.
52	4848 MARSHALL RD	Sidewalk at tree (2 panels) Use Trip Stop at this location
53	2100 PATTERSON BLVD	Remove pavers and place 6" concrete, near drive approach.
54	1457 CARDINGTON RD	SW PANEL